NOT FOUND

Report No. NADC-82075-60



# LPU-21/P LIFE PRESERVER CASING MATERIAL PROGRAM

Jules Z. Lewyckyj
Aircraft Crew Systems Technology Directorate
NAVAL AIR DEVELOPMENT CENTER

Warminster, Pennsylvania 18974

October 1982

**Final Report** 

MADC

Approved for Public Release; Distribution Unlimited

enfo.

19970604 094

DEED QUALUTY INSPERSED &

Prepared for
NAVOLAR SYSTEMS COM LAND
Deportment of the Navy
Washington, P.G. 20361

#### NOTICES

REPORT NUMBERING SYSTEM - The numbering of technical project reports issued by the Naval Air Development Center is arranged for specific identification purposes. Each number consists of the Center acronym, the calendar year in which the number was assigned, the sequence number of the report within the specific calendar year, and the official 2-digit correspondence code of the Command Office or the Functional Directorate responsible for the report. For example: Report No. NADC-78015-20 indicates the fifteeth Center report for the year 1978, and prepared by the Systems Directorate. The numerical codes are as follows:

CODE	OFFICE OR DIRECTORATE
00	Commander, Naval Air Development Center
01	Technical Director, Naval Air Development Center
02	Comptroller
10	Directorate Command Projects
20	Systems Directorate
30	Sensors & Avionics Technology Directorate
40	Communication & Navigation Technology Directorate
50	Software Computer Directorate
60	Aircraft & Crew Systems Technology Directorate
70	Planning Assessment Resources
80	Engineering Support Group

PRODUCT ENDORSEMENT - The discussion or instructions concerning commercial products herein do not constitute an endorsement by the Government nor do they convey or imply the license or right to use such products.

APPROVED BY

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION	PAGE	READ INSTRUCTIONS BEFORE COMPLETING FORM	
1. REPORT NUMBER	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER	
NADC-82075-60			
4. TITLE (and Subtitle)		5. TYPE OF REPORT & PERIOD COVERED	
LPU-21/P Life Preserver Casing Material Report		Final	
LFO-21/F Life Fleseiver Casing Waterial Heport		6. PERFORMING ORG. REPORT NUMBER	
		. PERFORMING ONG. REPORT NUMBER	
7. AUTHOR(e)		B. CONTRACT OR GRANT NUMBER(*)	
Jules Z. Lewyckyj			
oulds L. Lowyerry			
9. PERFORMING ORGANIZATION NAME AND ADDRESS		10. PROGRAM ELEMENT, PROJECT, TASK	
Naval Air Development Center	`	AREA & WORK UNIT NUMBERS	
Aircraft and Crew Systems Technology Director	ate		
Warminster, PA 18974			
11. CONTROLLING OFFICE NAME AND ADDRESS		12. REPORT DATE	
Naval Air Systems Command		October 1982	
Department of the Navy Washington, DC 20360		13. NUMBER OF PAGES 8	
14. MONITORING AGENCY NAME & ADDRESS(II different	from Controlling Office)	15. SECURITY CLASS. (of this report)	
		Unclassified	
		<u> </u>	
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE	
16. DISTRIBUTION STATEMENT (of this Report)			
Approved for Public Release; Distribution Unlin	nited		
Approved for Public Release, Distribution Offini	nteu		
17. DISTRIBUTION STATEMENT (of the abstract entered i	n Block 20 If different fro	m Report)	
17. DISTRIBUTION STRIEMENT (OF ING ADMITTED AND ADMITTED ADMITTED AND ADMITTED ADMITTED ADMITTED ADMITTED AND ADMITTED AND ADMITTED ADMIT	77 DIOCK 20, 11 UNITOTOTI 110	1	
18. SUPPLEMENTARY NOTES			
19. KEY WORDS (Continue on reverse elde il necessary and	d identify by block number)		
Aramid Plain Weave, Life Preserver	Helicopter Life	Preserver	
Aramid Twill, Life Preserver	Life Preserver		
Casing Material, Life Preserver	LPU-21/P Prese	rver, Life	
	Preserver, Life		
20. ABSTRACT (Continue on reverse side if necessary and	identify by block number)		
LPU-21/P Life Preserver Casings manufactured	from High Temperature	Aramid Cloth (MIL-C-81814) has a	
tendency to unravel at edges, making manufacture difficult with seam separation. A new Aramid Plain Weave			
Cloth (MIL-C-83429) does not unravel as easily	. A number of preserve	rs were manufactured from the new	
cloth and were given a special evaluation by ope	erational squadrons. Th	e casings withstood wear well and the	
new material would eliminate most of the ravel	ing and seam separation	problems.	

## TABLE OF CONTENTS

	Page 1	e No.
INTROD	OUCTION	1
DES	SCRIPTION	1
TES	ST PROCEDURE	1
RESULT	S AND DISCUSSION	. ຸ 1
GEN	NERAL	1
CON	NDITIONS OF WEAR	1
	AR	
MA	INTENANCE	4
	DWAGE	
	ERALL PERFORMANCE	
	NERAL COMMENTS	
	USIONS	
APPEND		
_	aluation Form: LPU-21/P Aircrewmen Life Preserver Casing Fabricated with L-C-83429, Type II, Class 1 Cloth (Contract No. N00383-80-C-4391)	A-1
APPEND		
Pilo MIL	ot Evaluations for Use of LPU-21/P Life Preserver Casing Material, L-C-83429 (Type II Class 1) (SH-3 Pilots in HS-1)	. B-1
	LIST OF FIGURES	
Figure		٠
1	MIL-C-81814 100% Nomex Aramid	2
2	MIL-C-83429 (Type II Class 1 ) 95% Nomex, 5% Kevlar	3
	LIST OF TABLES	
<u>Table</u>		
I	Comparison of Material Properties	4



#### INTRODUCTION

#### BACKGROUND

The present LPU-21/P Life Preserver Casing is manufactured from MIL-C-81814, High Temperature Resistant Aramid Twill Cloth. This particular form of NOMEX has a tendency to unravel at its edges, making a casing very difficult to manufacture and sewn seams separate after manufacture because of this unraveling. A number of preservers were manufactured from MIL-C-83429, Aramid Polyamide Non-Melting Plain Weave Cloth for a special evaluation by operational squadrons. This cloth does not unravel as easily as the filament fabric. Helicopter crews were given these life preservers and were asked to fill out questionnaires evaluating the new casings.

This program was authorized by the Naval Air Systems Command and had a priority listing on the "NAVAIR ALSS/ILS/AMP TASK/PRIORITY LIST" with a priority of II A-9 titled "Nomex cases on LPU-21/P life preservers unravel and separate at the seams."

#### DESCRIPTION

The original LPU-21/P Life Preserver Casings are manufactured from MIL-C-81814 cloth (figure (1)). The new casing material is MIL-C-82429 (figure (2)). A comparison of some differing properties is given in table I. Casings were manufactured to the same design as that for the LPU-21/P using the new material.

#### **TEST PROCEDURE**

Forty-three complete life preservers were forwarded to Helicopter Anti-Submarine Squadron ONE, Naval Air Station, Jacksonville, FL. Questionnaires were forwarded to the squadron to be filled out by wearers of the life jackets. The questionnaire is shown in appendix A.

#### RESULTS AND DISCUSSION

#### **GENERAL**


Fifty-six percent of the questionnaires were answered, all by pilots. Results of the questionnaires are summarized in appendix B.


#### CONDITIONS OF WEAR

The preservers were worn by pilots who were between 5 ft. 8 in. at 135 lb. and 6 ft. 3 in. at 200 lb. (The pilots had between 300 and 3200 hours of flying time in their careers with an average of 1938 hours). The preservers were worn during regular flight duties for between 20 and 150 hours with an average of 64 hours of wear.

#### **WEAR**

In general, the casings withstood wear very well. Seams separated in 16% of the preservers (84% showed no separation). Pilling occurred only in 5% of the preservers and fading or silk screening rubbing off occurred in only 5% of the preservers. Bindings pulled off in 9% of the preservers with 91% showing no damage.





#### TABLE 1 - COMPARISON OF MATERIAL PROPERTIES

	MIL-C-81814 "Cloth, Twill, Aramid, High Temperature Resistant"	MIL-C-83429 Type II Class I "Cloth, Plain and Basket Weave, Aramatic Polyamide Non-Melting"
Fiber	"Nomex" High Temp. Aramid, 200 Denier filament	95% Nomex, 5% Kevlar Non-melt Aromatic polyamide staple
Weave	2/2 right hand twill	Plain
Weight (oz/yd <sup>2</sup> )	5.2-5.6	4.3
Yarns/inch Warp	98 90	70 47
Denier/filament	2	1.5
Breaking strength (lb.) Warp Fill	185 160	180 100
Tear strength (lb) Warp Fill	13 . 13	12 8
Air Permeability (ft <sup>3</sup> /min/ft <sup>2</sup> )	12	25
Flame Resistance Flame Time (Sec) Glow Time (Sec.) Char Length (in.)	1 14 3.5	2 25 3.5
Stability after laundering (Max. shrinkage in %) Warp Fill	2 2	4 1.5

#### MAINTENANCE

No maintenance problems were encountered.

#### **STOWAGE**

About half of the pilots (52%) encountered problems in repacking the preserver in its casing. The bladder pushed out at the neck by opening up of the velcro. However, this problem was not caused by the new material; the tightness of the casing at the neck is part of the original LPU-21/P design.

#### **OVERALL PERFORMANCE**

Ratings were split at 1/3 each for "Very Good", "Good" and "Adequate".

#### **GENERAL COMMENTS**

About one-third of the questionnaires included "Comments". These were all favorable with regard to the new material.

#### CONCLUSIONS

In general, the new MIL-C-83429 material may be considered satisfactory for manufacture of LPU-21/P life preserver casings. It would eliminate the raveling and seam separation problems which occur with MIL-C-81814.

The problem with neck separation of the casing which allows the bladder to push out must be addressed by a minimal redesign of the casing.

#### APPENDIX A

#### **EVALUATION FORM**

# <u>LPU-21/P AIRCREWMEN LIFE PRESERVER CASING FABRICATED WITH MIL-C-83429, TYPE II, CLASS 1 CLOTH (CONTRACT NO. N00383-80-C-4391)</u>

#### INTRODUCTION

The LPU-21/P Life Preservers fabricated with MIL-C-83429 Type II Class 1 cloth have been produced to evaluate an alternative cloth to the MIL-C-81814 aramid cloth which is currently specified for use in the casing.

#### **PURPOSE**

The purpose of this evaluation is to collect data on user acceptance and operational suitability of LPU-21/P life preserver casings fabricated with MIL-C-83429 cloth. This information will be used to determine the suitability of this cloth for future procurements of life preserver casings. Your contribution to this evaluation is both important and appreciated. When you have completed this evaluation form, please return to:

Commander Naval Air Development Center Code 60313 Warminster, PA 18974

1.	Name and Rank	2. Date
3.	Organization/Squadron	
4.	Aircraft Type	
5.	Height 6. Weight _	
7.	Crew Position:	
	Pilot RIO/NFO	Other
8.	Your approximate total flight hours	
9.	Approximate total hours the evaluation item was worn	
10.	Describe the overall performance of the life preserver during flight.	
	Very good Good Adequate Poor	Very Poor

11.	Were any of the following fa	ilures observed duri	ng the evaluation period	?
	Seam Separation	Yes	No	
	Excessive Pilling	Yes	No	
	Pulling off of Bindings	Yes	No	
	Fading or Rub-off of Silk Screened Information	Yes	No	
	Comments:			
	•			
•				
12.	Were there any maintenance			
	If so, describe			
13.	Did you observe any probler Yes No	ms with the stowage	of the life preserver in t	the casing?
	If so, describe	•		
	11 50, describe			
		',		
1/	Overall Comments or Recor			
14.	Overall Comments of Necor	mineridations.		
			-	

#### APPENDIX B

### PILOT EVALUATIONS FOR USE OF LPU-21/P LIFE PRESERVER CASING MATERIAL, MIL-C-83429 (Type II Class 1) (SH-3 PILOTS IN HS-1)

PILOTS: 5 ft. 8 in./135 lb. to 6 ft. 3 in./200 lb.

Total Flight Hours: 300-3200; Average – 1938 Hours LPU-21/P Worn: 20-140; Average – 64

\*OVERAL PERFORMANCE RATINGS: Adequate - 33% Good - 33% Very Good - 33%

#### \*WEAR:

Seam Separation	No - 84%	Yes - 16%
	No - 95%	Yes - 5%
Pulling Off Binding	No - 91%	Yes - 9%
Fading/Silk Screen Rub Off	No - 95%	Yes - 5%

MAINTENANCE PROBLEMS: None.

\*STOWAGE PROBLEMS: No - 48%; Yes - 52%

<sup>\*</sup>Figures given are for percentage of respondents answering each question.

	No. of Copie	S
Commander, USAADC (ATSA-CD)		1
Commander LICAIC /ATCH CD)		
Commander MP CMI SCH TNGCEN (ATZN-CM)		1
Commander USASIC CTR (AT7H-CD)		1
Commander, USA Institute for Military Assistance (ATSU-CD)		3
Commander, USAARMC (ATZK-CD/ATZK-ADD)		1
Commander, USAEC (ATSE-CTD)		1
Commander, USAFAC (ATSF-CTD)		1
Commander, USAINCS (ATSI-CTD)		1
Commander, U.S. Ordnance Ctr & Sch (DCD)		1
Commander, U.S. Ordnance Ctr & Sch (DCD)		1
Commandant, USATSCH (ATSP-CD)		1
Commandant, USATSCH (ATSP-CD)		•
Commander, U.S. Marine Corps Dev. & Ed. Command, Dev. Ctr.		1
(M&L Div)(M&L Div)		1
Commander, USAF SYS. COMMAND (SDNE)		1
Commander, USARIEM (SGRD-UE-ME)		1
Commander, USATARCOM (DRCPO -ALSE/DRSTS-T)		1
A DAIGD GAC (MCD AVALL)		
HQDA (DAMO-NCC/DAMA-ZC/DASG-PSP/DAMO-RQD).		1
Committee LICAADI (CCDD IIAC)		•
- 1. LICACO		
O in the state LICADELLD & 7th Army / AFAGC-AV/AFAGC-NU).		_
Commander USAEORSCOM (AEOP-AV/AEOP-TAS)		~
$C_{\text{max}}$		•
On an and an MECTCOM (A EOD-AV)		,
Oden UCAUEI /DDYUE.EA)		- 1
A LIO TAC/DDDC /MAl/Groppard\ Langley AFB		
a L FDADCOM (DDDEL CM)		
• 11 Diamand I ob /DEI UD N.DI		
a LICA Facilian montal Hygiona Agancy (HSF-R)		
0		-
- 1000000000000000000000000000000000000		
- LICATECOM (DDCTE AV)		
0		
Commander USALFA (DALO-LEI)		. 1
o I'm Canamal II C Army Agramadical Research II ab		
/ A === 0 \		. 1
- u o 1 110 ACD Wright Dottorcon AFB		
O manufact Congress LLS Army Aviation Systems Command		
* O1 IIO Fitth Army		
Commanding General, H.C., Fifth Army Combat Developments Activity		. 1
- W ACC B SIN Taylor Noval Ship Mccarch		
and Development Center		. 1
(1 for Fire Fighting and Survivability Brailett)  Commanding General, U.S. Army Agency for Aviation Safety		. 1
- 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		. 1
Commanding General, U.S. Army Flight Facility		
Commanding General HO TRADOC. (ATCD)		. :

	N	ο.	0	f	C	o	pi	ies
·								
Commanding General, HHC	٠.	•	• •		•	•	•	. 1
David Clark Company Inc.						•	•	. 1
ayne Inc	• •	•	• •			•	•	. !
Grumman Aerospace Corp.	٠.	•	• •	• •	•	•	•	. 1
ockheed Aircraft Corp.	• •	٠	• •		•	٠	•	. 1
Inited Aircraft Corn		•				•	•	. 1
Seneral Dynamics Corn						•	•	. 1
AcDonnell Douglas Corp		•	• 1		•	٠	٠	. 1

		No. of Copies
U.S. Dept. of the Interior, Office of Aircraft Services.		1
(1 for L. Langdon)		
W.L. Gore & Associates, Inc.		3
Dayton T. Brown, Inc.		
(1 for Test Laboratory Division)		
Commanding Officer, VC-13		2
Commanding Officer, VF-302		2
Commanding Officer, Fighter Squadron THREE ZER	O TWO	2
Commanding Officer, HELSUPPRON ONE		1
Commanding Officer, Naval Regional Medical Center,		
Portsmouth		1
Commanding Officer, NAS North Island .		1
(1 for Code 582)		
Commanding General, 3rd MAW (FMFPA)		1
Commanding General, 1st MAW, FMFPAC_	U 820 0395	1
Commanding General, MAG-24, 1st N	3 3 3 3 3 3 3 3	1
Commander, COMFITAEWWINGPA N.A.D.C.		1
(1 for Code 81) NADC-8	32075-60	_
Chief of Naval Air Training		1
(1 for Code 5113)		
Commander, Naval Air Force U.S. /		1
(1 for Code 522E)		
Commanding Officer, HC-16		1
Commanding Officer, HC-1		1
Commanding Officer, Naval Air Eng		1
(1 for Code 9312)		
Commanding Officer, MAG-31		1
Officer In Charge, Branch Clinic, N		2
Commanding Officer, Naval Weapor		2
(2 for Code 3023)		
Commanding Officer, HS-84		1
Commanding General, 2nd Marine /		1
Commanding Officer, MAG-26, 2nd		1
Officer in Charge, Naval Sea System		
Combatant Craft Engineering Dep		3
Director, National Aeronautics and		3
Commandant, U.S. Coast Guard He		
Research & Development		3
Officer In Charge, U.S. Navy Clothi		
Facility Natick		3
Canadian Armed Forces, National E		1
Commanding Officer, Naval Avionics Center		1
(1 for Code D432)		
Commander, USANVL, (DELNV-D/DELNV-SI), For	t Belvoir, VA	<i>.</i> 1
Commander, CSL (DRDAR-CL/DRDAR-CLW), Aber	deen Proving	
Ground, MD		
Commander, USADARCOM (DRCNC/DRCDE-DG/D	RCDE-DH/DRCDE-BSI)	
Commander, USACAC (ATZL-CAM-IM/ATZL-CAM-	·IC)	
Commander, USALOGC (ATCL-MPP/ATCL-MS)		1

## DISTRIBUTION LIST

## REPORT NO. NADC-82075-60

	No. of Copies	•
Commander, Chief of Naval Operations		*
Commander, Naval Air Systems Command	6	
(1 for AIR-340B)		
(1 for AIR-09E)	2	
Commanding Officer, Naval Aviation Schools Command		
Commanding Officer, FASOTRAGRUPAC	2	
Commander, Naval Weapons Center :		
(5 for Code 6412)	1	
Commander, Pacific Missile Test Center		
(1 for Code 1131)	2	
Commander, Naval Safety Center	1	
(1 for Code 421)		
Commanding Officer, MAWTS-1	1	
Commanding Officer, Aviation Supply Office	3	
/2 for Codo TEO/// /\		
Commander, Naval Air Force, U.S. Pacific Fleet	3	
(1 for Mr. Ben Withers)		
(1 for Code 7212)		
(1 for Code 711)		
Officer In Charge, Naval Regional Medical Center Aviation	1	
Physiology Training Service	2	
Commanding Officer, U.S. Coast Guard Air Station, San Diego	2	
Marine Corps Development & Education Command Air Branch, Fire Power Division, Development Center	2	
(2 for Code D09-2)		
Commander, Light Attack Wing Pacific	1	
(1 for Code 9733)		
Commanding Officer Naval Air Technical Services Facility	1	
Commanding Officer, Naval Air Rework Facility	1	
(1 for Code 3331)		
Commanding Officer, H&HS-48 MACG-48	2	
Commanding Officer, Naval Air Rework Facility, Naval	2	
Engineering Support Office	2	
(2 for 23de 321) Commanding Officer STRON THREE ZERO ONE	2	
Commanding Officer TRON THREE ZERO ONE		
(a) for Co. (37)		
H. Koch & Sons, Anahein, CA	J	/
(1 for J. A. Muklevýcz)		,
onax Corp		
(1 for S. J. Wojdan)		SA S
IL Dover		<b>\$</b> >ones
(1 for R. Desposier)	And the second	
	A STATE OF THE STA	
	A Comment	
		<b>₩</b>
	No.	1